



HDF4-5

Payload 4 Kgf


Installation method		Application	
Floor	●	Spot welding	
Ceiling	●	Arc welding	
Wall surface		Handling	●
Angle	●	Assembly	●
		Sealing	●
		Painting	



View A,F : Detailed drawing of the wrist attachment part




View B: Dimensional drawing for the floor installation of the body





※ Precaution : When installing robot, please apply positioning pins. (2xØ6)


Wrist-axis torque line diagram



View E, G: Details of the application ancillary part



View D: Application cable connection



** For product improvement, some of the ratings, specifications, dimensions, etc. are subject to changes without notice.