






Flange mounting holes



Base mounting holes



10-pin client cable
2- $\phi 4$ trachea



(The position of the side extended overload connector should be designed to leave an additional 120mm of space.)